


Version 2.2.51.0 or above: Could not create SSL/TLS secure channel (Konica Minolta Integrated)

Prior to version 2.2.51, the OpenAPI SDK used a default SSL protocol that would often result in an error during the initialisation of a device (Could not create SSL/TLS secure channel). To fix this, either a registry change was required on the machine where Resource Manager is running (see **Version 2.2.50.1 and below: Could not create SSL/TLS secure channel**), or a special firmware was required for the device.

PD version 2.2.51 (or above) should not suffer from the problem described above because it supports TLS 1.2. However, it has been reported that a similar problem occurs, and the fix described in **Version 2.2.50.1 and below: Could not create SSL/TLS secure channel** does not resolve the problem.

Symptoms

After clicking **Gather Info**, the following text appears in the output box:



This prevents the device from being Initialised.

Cause

Because PD supports TLS 1.2 and it is enabled on the device, the OpenAPI AppReq messages will attempt to use TLS 1.2. However, on the device in question (C3350, Controller ROM Version: A3GN30G0803-W99, Engine ROM Version: A3GN0Y00050G001900) the TLS 1.2 implementation was not working.

Resolution

Log in to the web interface of the device in Administrator mode. Disable **TLS 1.2**:

The screenshot shows the Konica Minolta Web Connection interface. At the top left, it displays the Konica Minolta logo and 'PAGE SCOPE Web Connection' with the model name 'bizhub C3350'. On the top right, it shows the user 'Administrator' and two 'Ready' status indicators. Below the header is a navigation bar with tabs for System, Security, Job, Print, Storage, Address, and Network. The 'Security' tab is selected, and the 'SSL/TLS Settings' section is expanded. The settings include: 'SSL/TLS' set to 'Enable', 'Encryption Strength' set to 'AES-256, 3DES, RC4-128', and 'SSL/TLS Version' with checkboxes for SSL 3.0, TLS 1.0, TLS 1.1, and TLS 1.2. The 'TLS 1.2' checkbox is highlighted with a red box.

Now log out of the device and attempt the **Gather Info** again. The initialisation should succeed.

Document revision date: 2022/06/21
Software version: 2.2.51.1
© 2022 Blue Swift Software CC